

Single Window

Measure windows accurately using metal tape

- A** - From ceiling to top of window frame. If you have crown molding do measurement "**B**" instead of "**A**".
- B** - From bottom of crown molding to top of window frame.
- C** - Top of window frame to floor.
- D** - Outside of window frame to outside of window frame.
- E** - Free wall space to left of window.
- F** - Free wall space to right of window.
- G** - Top of window casing to top of glass.
- H** - Glass width.

